



Staircases

Problem - Treat existing staircase in conversion to reduce sound and prevent trip hazard

Solution - InstaCoustic stair system

Acoustic Stair System



Key Issues

Staircase that is receiving the 108, 208 OR H203 stair system must be:

- Free of all debris and sharp objects
- Loose or creaking stairs must be screwed down and gaps sealed